

FISSO ghost


EN invisible fastener with fit-up aid. when you want to hide the fastener and you cannot or will not have holes in your sign. post the polycarbonate fastener using the removable leaves on your sign, fasten it with screws, glue, tape or silicone, mark the boreholes on the wall using the smart adhesive stickers, wallmount the spacers and click in the sign.

mounting: click system, invisible, for signs without holes, quick to change, easy to mount. material: polycarbonate, brass nickel-plated. wall distance: 20mm. sign thickness: no limit.


product nr.



ghost
FG4618K




on the wall






spacers can be mounted to the sign with appropriate glue



with adequate material mounting with screws is possible



double faced adhesive tape to fix the spacers with the sign



silicone can also be used without problem

please test every application if suitable for material and weight.

